



U.S. Department
of Transportation
**Federal Aviation
Administration**

Western Pacific Region
Riverside Flight Standards District Office

6961 Flight Road
Riverside, California 92504
Phone: (951) 276-6701
Fax: (951) 689-4309

November 23, 2020

Craig Garrick
CEO/Accountable Manager
COMAV Technical Services
18438 Readiness Street
Victorville, CA 92394

Dear Mr. Garrick:

This office has received your submitted Transport Canada Civil Aviation (TCCA) Maintenance Implement Procedures (MIP) Supplement to your Repair Station Manual, Revision Original dated 11/10/2020. Upon review, we find the TCCA MIP Supplement meets the requirements of Maintenance Implementation Procedures (U.S.-Canada), Rev 1, dated June 14, 2019; and **is accepted.** This office has retained a copy of the supplement for our files.

Should you have any questions, I can be reached at telephone 951-276-6701 ext. 323. Our office hours are from 7:30 am to 4:00 pm Monday thru Friday.

Sincerely,

PK
Patrick J. Gates
Principal Maintenance Inspector